



BLIKSUND

CASE 2

Head-on collision between two lorry combinations





Incident	July 2025, Maasdijk, Hoeksebaan / N223 Two lorry combinations collided head-on after one of the drivers was taken ill
Weather	SW / 2 Bft / 25°C / dry
Vehicle(s)	Volvo (16-BXP-6) and Scania (24-BLV-1)
Particulars	The driver of the red lorry has his legs badly trapped in the dashboard. The lorries can no longer be moved.
Decision tree exercise	Branch out based on choices such as: - Start on arrival at the scene; - Casualty responsive yes/no, and what does that mean? - Vehicle unstable yes/no, and how will you solve that? - Fuel leaking yes/no, what can you do about it? - Alternative fuels involved yes/no, what does that mean for the operation? - Which safety systems are present and what influence do they have? - What other points of attention do you see in this accident? - What are the emergency scenarios? - What help and support need to be arranged?

<https://regio15.nl/nieuws/ongevallen/38433/wegvervoer-ongeval-letsel-hoeksebaan-220725/>